

P-03 High rate of CT failure

1	Name of Company	Gujarat Energy Transmission Corporation Limited	
2	Title (Problem)	High rate of CT failure.	
3	Brief details about the problem	In our GETCO network, 66KV class CT failure rate is very high during the month of March to June. We want to analyze the failure rate for preventive maintenance or identification of technical deficiency.	
4	Category of Problem	√ Technical / Information Tech / Human Resource / Other	
5	Details about Coordinating Officers	Coordinating Officer – 1 Shri R. D. Naik	Coordinating Officer – 2 Shri A. K. Malek
	Mobile No	99252 08064	99789 36144
	E-mail ID	kpi_trans@gebmail.com	eetrvii@gebmail.com
	Designation	Additional Chief Engineer	Executive Engineer
	Place of Working	Vadodara	Vadodara